



CAIRO TOWN WORKSHOP December 20, 2023

PLEDGE OF ALLEGIANCE

MINUTES: November 6, 2023 Board Meeting Minutes
December 4, 2023 Board Meeting Minutes

New Business:

1. Amend Local Law #4 of 2018 – Caro Zoning Law for Main Street Commercial District

Resolutions:

- 2023-234 Approve Expenditure Account Adjustments for 2023 Budget
- 2023-235 Accept EDU Billing
- 2023-236 Approve to Purchase New Printer – Town Clerks Office
- 2023-237 Approve Highway Department to Purchase Used Printer
- 2023-238 Approval of Naming a Private Road
- 2023-239 Authorize Public Hearing – Amend Local Law #4 of 2018
- 2023-240 Approve No. 2 Heating Oil Contract
- 2023-241 Set Re-Organizational Meeting for January 3, 2024
- 2023-242 Amend 2023 Budget to Correct Balances on Expenditure Accounts

Monthly Reports:

1. Highway Report – November 2023

Report of Committees –

Jason Watts -	Code/Building/Zoning Planning Board Parks, Buildings & Grounds
Mary-Jo Cords -	Assessor Insurance/Health Insurance Library Community Center
Debra Bogins -	Highway Water/Sewer
Tim Powers -	Ambulance Animal Control Greene County EMS
Michael Flaherty –	Courts Police Festivals/Parades/Youth Fair



Art Evans
Town of Cairo Highway Superintendent
755 Route 145
Cairo, NY 12413
518-622-9515
518-622-3185 Fax
518-965-1266 Cell
highwaysuper@townofcairo.com

Highway Report



November 2023

- Work on non-reflective road signs being replaced is ongoing.
- Brush trimming is ongoing.
- Highway currently has 9 full time employees 7 with CDL's.
- Received Tandem Axle dump truck from County.
- Salt and sand sheds are full and prepped for winter.
- Trucks are outfitted with plows and sanders.

Upcoming projects

It's all about snow removal
Trucks being dressed with plows and sanders.

Trucks currently down as of 11/30/2023

- 01 – Ford F350 Exhaust leak on manifold. Too costly to repair. Driven as is. (\$4,400)
- 02 – Ford F350 Exhaust leak on manifold. Too costly to repair. Driven as is.
- 32 – Wheel bearing, front end wear issues. Retired.

Plow Trucks

- 09 – Ford - Exhaust leaking into cab.
- 02 – Ford - Sander not working.
- 05 – International – Hydraulic leak.
- 12 – Side dump piston leaking. Awaiting new piston.
- 13 – Mack – Coolant leak. Waiting on part.
- 14 – Mack – Electrical issue. Waiting on diagnosis.
- 15 – Mack – Power steering leak. Waiting on part.
- 16 – International – Transfer case. Waiting for parts at Hilltop.
- 18 – Oshkosh. Brake drums and 2 broken wheel studs. – Retired.
- 21 – Ford – 4x4 not working.
- 26 – Sterling –Side dump hinge rotted.
- 35 – Sterling – Awaiting exhaust pipe.